

Interim Reclamation Inspection

August 17, 2021

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 427862

Inspection Document #: 697503175

Weld County, CO

SESW Section 8 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brown /13-8
Location ID: 427862



Photo 1. Photo taken from the northeast deadman, facing South. Photo illustrates unmanaged weeds within the deadman.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503175

Inspection Photos
Location Name: Brown /13-8
Location ID: 427862



Photo 2. Photo taken from the northeast deadman, facing West. Photo illustrates unmanaged weeds within the deadman. Red arrow pointing to northwest deadman.



Inspection Photos
Location Name: Brown /13-8
Location ID: 427862



Photo 3. Photo taken from the southwest deadman, facing East. See comments under Photo 1 and 2.

Inspection Photos
Location Name: Brown /13-8
Location ID: 427862



Photo 4. Photo taken from the western location, facing South. See comments under Photo 1 and 2.



Inspection Photos
Location Name: Brown /13-8
Location ID: 427862



Photo 5. Photo taken from the northwestern location, facing Southwest. See comments under Photo 1 and 2.

