

Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696



Colorado Oil & Gas Conservation Commission
40.37115, -104.74441, 1428.2m, 164°
Sep 1, 2021 12:07:18 PM

Photo 1: Tank Battery signs



Colorado Oil & Gas Conservation Commission
40.37121, -104.74424, 1423.4m, 197°
Sep 1, 2021 12:06:57 PM

Photo 2: Tank Battery



Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696




Photo 3: Wellhead Sign



Photo 4: Stained soil

Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696



Photo 5: Stained soil



Photo 6: Stained soil



Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696



Photo 7: Weeds at each wellhead



Photo 8: Weeds at each wellhead

Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696



Photo 9: Weeds



Photo 10: Tank not grounded



Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696



Photo 11: Unused/disconnected equipment



Photo 12: Unused/disconnected equipment



Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696



Photo 13: Unused equipment



Photo 14: unused insulation

Inspection Photos
Location Name: Evans 7-26 Pad
Location ID: 441696




Photo 15: Unused/disconnected risers



Photo 16: Unused/disconnected risers