

Interim Reclamation and Stormwater Inspection

August 26, 2021

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 436860

Inspection Document #: 697503183

Weld County, CO

NWSW Section 27 T6N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources_S




Photo 1. Google Earth aerial imagery from 9/7/2013. Photo illustrates the current outer perimeter of the location (red line) of ~ 5.30 acres for the two drilled wells. Operator has performed interim reclamation activities; however, the size of the location can be further reduced in size. For illustrative purposes, an ~75 foot circle has been generated around the circumference of the southern well for potential workover rig space. Note- some of the southwestern area may be needed for vehicle traffic but Operator should reconsider location entrance to help further reduce the size of the southwestern area.

Inspection Photos

Location Name: Pappenheim C-W2 6-62-27_26

Location ID: 436860



Photo 2. Drone aerial imagery illustrates the two wells, the location entrance and the southwestern location. Operator should reconsider location entrance to help further reduce the size of the southwestern area, illustrated here.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503183

Inspection Photos

Location Name: Pappenheim C-W2 6-62-27_26

Location ID: 436860



Photo 3. Drone aerial imagery illustrates the eastern location. Operator has performed interim reclamation activities; however, the size of the location can be further reduced in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503183



Photo 4. Drone aerial imagery illustrates the two wells and the north/northeastern location. See comments under Photos 1-3.

Inspection Photos

Location Name: Pappenheim C-W2 6-62-27_26

Location ID: 436860



Photo 5. Photo taken from the southeastern perimeter of location, facing Northwest. Photo illustrates the size of the location can be further reduced in size.

Inspection Photos

Location Name: Pappenheim C-W2 6-62-27_26

Location ID: 436860



Photo 6. Photo taken from the southeastern perimeter of location, facing West. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503183