

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2021

Submitted Date:

09/03/2021

Document Number:

697601517

FIELD INSPECTION FORM

Loc ID 305426 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , Anadarko | | COGCCinspections@Anadarko.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|-------------------------|-------------|
| 476957 | TANK BATTERY | AC | 07/14/2020 | | - | Dechant 29 NENE battery | EI |

General Comment:

production facilities at battery inspected. Well(s) served by battery are not colocated with production facility and wells not inspected in this report.

Location

Overall Good:

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-----------------|
| Emergency Contact Number: | |
| Comment: | on battery sign |
| Corrective Action: | |
| Date: | _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: no spills observed at surface during inspection

Multiple Spills and Releases?

| | | | |
|--------------------|-------------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|--------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | earthen berm | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|--------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLs | PBV CONCRETE | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | | Adequate |
| Comment: berm shared with crude tank | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.116487,-104.680644 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Wells Served By Facilities Above

| |
|------------|
| API Number |
| 123-25349 |
| 123-25348 |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|----------|--|
| Type | |
| Comment: | |

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 476957 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 697601518 | crude tank, PW vessel and battery sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523967 |
| 697601519 | separator, ECD and Gas meter run | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523968 |