

# Inspection Photos

API: 071-08481

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021

## Inspection Photos



**Photo 1.** Facing north at the beginning of the access road. There is erosion occurring down the road and the side of the road is not stabilized. The sides of the road need to be seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021

## Inspection Photos



**Photo 2.** Facing back south at the beginning of the access road. There is erosion occurring down the road and the side of the road is not stabilized. Stormwater directed down the road is causing erosion which is shown in the next photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021

## Inspection Photos



**Photo 3.** This erosion has occurred from stormwater directed down the road. This is also depositing sediment down the road below shown on photo 6.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021

## Inspection Photos



**Photo 4.** There is deep erosion channel in the road caused from stormwater flowing down the road. Stormwater needs to be properly diverted with ditches, water bars, ect. and velocity needs to controlled with check dams sediment traps ect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021

## Inspection Photos



**Photo 5.** The white hard hat is placed in the erosion channel for scale.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021

## Inspection Photos



**Photo 6.** Stormwater is directed to this area from the access road switch back above.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021

## Inspection Photos



**Photo 7.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08481 | Date: 9/3/2021