

# Inspection Photos

API: 071-08652

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08652 | Date: 9/3/2021

## Inspection Photos



**Photo 1.** There is vehicle rutting and erosion along the main road near the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08652 | Date: 9/3/2021

## Inspection Photos



**Photo 2.** Facing toward the production equipment at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08652 | Date: 9/3/2021