

# Inspection Photos

API: 071-06190

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06190 | Date: 9/3/2021

## Inspection Photos



**Photo 1.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06190 | Date: 9/3/2021

## Inspection Photos



**Photo 2.** There is oil stained soil around the engine skid that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06190 | Date: 9/3/2021