

Inspection Photos
Location Name: Martin T Hart D #2
Location ID: 336344



Photo 1 WH sign



Photo 2 dead weeds & stained soil around WH

Inspection Photos
Location Name: Martin T Hart D #2
Location ID: 336344



Photo 3 Pump Jack



Photo 4 dead weeds around ancillary equipment

Inspection Photos
Location Name: Martin T Hart D #2
Location ID: 336344



Photo 5 stained soil around WH



Photo 6 dead weeds around pump jack base

Inspection Photos
Location Name: Martin T Hart D #2
Location ID: 336344



Photo 7 dead weeds around pump jack base




Photo 6 dead weeds around pump jack base