

**Inspection Photos**  
**Location Name: Knowlton 5**  
**Location ID: 312764**



**Photo 1. Overview of location taken facing south.**



Inspection Photos  
Location Name: Knowlton 5  
Location ID: 312764



Photo 2. Stained soil at wellhead.



Photo 3. Some tank labels faded and no longer legible.

