

Inspection Photos
Location Name: Foster State 1
Location ID: 442674



Photo 1. Overview of location taken facing west. Livestock feeders visible on left side of photo.



Inspection Photos
Location Name: Foster State 1
Location ID: 442674



Photo 2. Cuttings stored on location. Sediment migrating onto location.



Photo 3. Cuttings stored on location. Sediment migrating onto location.

Inspection Photos
Location Name: Foster State 1
Location ID: 442674



Photo 4. Collapse in fill on west side of location. Sediment leaving location.



Photo 5. Access road overgrown.

