

Inspection Photos

API: 055-06157

Operator: PETROGLYPH OPERATING CO

Inspection Date: 8/31/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 8/31/2021

Inspection Photos



Photo 1. Facing north toward the access road. Sign remains at entrance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 8/31/2021

Inspection Photos



Photo 2. Facing northwest along the access road. This erosion area has not been repaired and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 8/31/2021

Inspection Photos



Photo 3. Facing northwest. The location had been reclaimed and perennial vegetation has re-established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 8/31/2021

Inspection Photos



Photo 4. Facing west toward the location. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 8/31/2021

Inspection Photos



Photo 5. Facing southeast toward the location. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 8/31/2021

Inspection Photos



Photo 6. Facing east toward the location. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 8/31/2021