

# Inspection Photos

9/03/2021

Operator: CAERUS ENERGY SERVICES LLC -  
10668

Location ID: 458475  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC - 10668

Location ID: 458475



September 3, 2021  
39.6936112N 108.12573772W

**Photo 1:** Photo of wells on the Location. Ongoing subsequent operations in process at time of inspection.

Inspection Photos  
Operator Name: CAERUS ENERGY SERVICES LLC - 10668  
Location ID: 458475



**Photo 2:** Photo shows signage missing from battery, and labeling missing from tanks.

Inspection Photos  
Operator Name: CAERUS ENERGY SERVICES LLC - 10668  
Location ID: 458475



**Photo 3:** Photo taken from the east end of the Location. Photo shows bag of trash improperly stored on Location.

## Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC - 10668

Location ID: 458475



**Photo 4:** Photos taken from the stockpiled soils on the north end of the Location. BMPs to prevent weed establishment on stockpiled soils is missing or insufficient; vegetation on soil stockpiles predominantly undesirable plant species. Little desirable plant germination/establishment observed.

## Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC - 10668

Location ID: 458475



**Photo 5:** Photos taken from the east end of the Location. Photos show containment BMP at base of cuttings is no longer in proper functioning condition; cutting material can be seen outside of containment.

Inspection Photos  
Operator Name: CAERUS ENERGY SERVICES LLC - 10668  
Location ID: 458475



**Photo 6:** Photo taken from the north end of the Location. Photo shows containment BMP at tanks is not in proper functioning condition to contain a spill.