

Inspection Photos
Location Name: Surprise Central Facility
Location ID: 436676



Photo 1. No label on storage tank.



Inspection Photos
Location Name: Surprise Central Facility
Location ID: 436676



Photo 2. Battery sign incomplete.



Photo 3. Battery signs incomplete.