

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2021

Submitted Date:

09/10/2021

Document Number:

697004544

**FIELD INSPECTION FORM**Loc ID 326874 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
| ,            |       | COGCCInspections@Oxy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 246003      | WELL | SI     | 06/01/2021  | GW         | 123-13799 | WOLF UPRR 32-31 | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |

|                           |                  |       |                 |
|---------------------------|------------------|-------|-----------------|
| <b>Equipment:</b>         |                  |       | corrective date |
| Type: Pig Station         | # 1              |       |                 |
| Comment:                  |                  |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Ancillary equipment | # 1              |       |                 |
| Comment:                  | Automation array |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Gas Meter Run       | # 1              |       |                 |

|                                   |  |  |       |            |
|-----------------------------------|--|--|-------|------------|
| Comment:                          | Calibration card is outdated. Meter not calibrated annually. See attached photo. |  | Date: | 12/13/2021 |
| Corrective Action:                | Calibrate gas metering equipment annually to comply with rule 430.d.(1).         |  | Date: |            |
| Type: Bird Protectors             | # 1  |  |       |            |
| Comment:                          |  |  | Date: |            |
| Corrective Action:                |  |  | Date: |            |
| Type: Horizontal Heated Separator | # 1  |  |       |            |
| Comment:                          |  |  | Date: |            |
| Corrective Action:                |  |  | Date: |            |
| Type: Flow Line                   | # 1  |  |       |            |
| Comment:                          |  |  | Date: |            |
| Corrective Action:                |  |  | Date: |            |
| Type: Plunger Lift                | # 1  |  |       |            |
| Comment:                          |  |  | Date: |            |
| Corrective Action:                |  |  | Date: |            |
| Type: Bradenhead                  | # 1  |  |       |            |
| Comment:                          | Bradenhead valve is exposed at surface.  |  | Date: |            |
| Corrective Action:                |  |  | Date: |            |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | #                                | Capacity | Type           | Tank ID | SE GPS |
|--------------------|----------------------------------|----------|----------------|---------|--------|
| PRODUCED WATER     | 1                                | 100 BBLs | PBV FIBERGLASS |         | ,      |
| Comment:           | Produced water tank is anchored. |          |                |         |        |
| Corrective Action: |                                  |          |                |         |        |

**Paint**

|                 |          |  |
|-----------------|----------|--|
| Condition       | Adequate |  |
| Other (Content) |          |  |

|                  |  |
|------------------|--|
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 246003 Type: WELL API Number: 123-13799 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/26/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 12Fluid Type: NoneEnd Surf Csg Pressure: --

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697004545    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5528269">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5528269</a> |