

Final Reclamation Inspection

September 7, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322875

Inspection Document #: 697503234

Weld County, CO

NWNE Section 18 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CARLSON #18-1
Location ID: 322875



Photo 1. 2015 aerial imagery illustrates active operations. Photo illustrates the well location, well location access road and associated offsite tank battery.

Inspection Photos
Location Name: CARLSON #18-1
Location ID: 322875



Photo 2. Photo taken north of the well location and well location access road, facing South. Photo illustrates the well location and well location access road are reflective of reference crop areas.

Inspection Photos
Location Name: CARLSON #18-1
Location ID: 322875



Photo 3. Photo taken from the associated offsite tank battery, facing East. Photo illustrates final reclamation has been performed; however, crop growth is stunted throughout the entire tank battery.



Inspection Photos
Location Name: CARLSON #18-1
Location ID: 322875



Photo 4. Photo taken from the associated offsite tank battery, facing West. See comments under Photo 3.