

Inspection Photos
Location Name: Pstasnik LC 20-75H
Location ID: 422561



Photo 1 – Wellhead

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Pstasnik LC 20-75H
Location ID: 422561



Photo 3 – Tanks STILL missing Capacity Labels. North Tank also missing Contents Label

Photo 4 – Separators and ECDs

Inspection Photos
Location Name: Pstasnik LC 20-75H
Location ID: 422561




Photo 5 – Stained Soil at Compressor Drain Pit