

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 3 Stained soil by WH



Photo 4 Unused electric panel leaning on the fence



Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 5 ancillary equipment



Photo 6 Unused electric panel leaning on the fence

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 7 Pump Jack