

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 3 Stained soil by WH



Photo 4 Unused electric panel leaning on the fence

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 5 spotty weeds by ancillary equipment



Photo 6 Weeds growing around Unused electric panel.

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 7 weeds around location



Photo 8 weeds growing by the WH

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133




Photo 9 weeds around location



Photo 10 weeds growing by the PJ base

Inspection Photos
Location Name: Oskarson #3
Location ID: 333133



Photo 11 weeds around location