

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 1 WH sign



Photo 2 Stained soil has been cleaned around WH

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 3 Pump jack



Photo 4 Stained soil has been cleaned around PJ base

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 5 TB sign



Photo 6 TB

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 7 Stained soil has been cleaned from around valve on South side of crude tank



Photo 8 Stained soil has been cleaned from around locked cellar


Inspection Photos

Location Name: Our Diane 31-27

Location ID: 328043



Colorado Oil & Gas Conservation Commission
8000 Morningside Dr, Erie, CO 80516, USA
40.11659, -104.98738, 4923.0ft, 181°
09/14/2021 12:41:22



Colorado Oil & Gas Conservation Commission
8000 Morningside Dr, Erie, CO 80516, USA
40.11658, -104.98742, 4921.9ft, 240°
09/14/2021 12:42:01

Photo 9 Gas Meter Run

Photo 10 Card in meter house indicates that calibration is not current