

Mull Drilling Company INC, BSR A 1-19
073-06779

Inspection #688311236

9/14/2021

Construction Inspection



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Garmin placed
next to well
stake.

Colorado Oil and Gas Conservation Commission
38.99109, -103.37746, 4836.0ft, 86
09/14/2021 10:38:33 AM



Drill pit.

Colorado Oil and Gas Conservation Commission
38.99086, -103.37763, 4852.4ft, 214°
09/14/2021 10:50:17 AM



Inside edge of drill
pit.

Colorado Oil and Gas Conservation Commission
38.99066, -103.37789, 4862.2ft, 245°
09/14/2021 11:18:11 AM



East topsoil
pile.

Colorado Oil and Gas Conservation Commission
38.99108, -103.37746, 4875.3ft, 91°
09/14/2021 10:41:39 AM



North topsoil
pile.

Colorado Oil and Gas Conservation Commission
38.99086, -103.37764, 4855.6ft, 317°
09/14/2021 10:50:22 AM



South
topsoil
pile past
pit.

Colorado Oil and Gas Conservation Commission
38.99085, -103.37764, 4855.6ft, 166°
09/14/2021 10:50:26 AM



Colorado Oil and Gas Conservation Commission
38.99128, -103.37712, 4839.2ft, 197°
09/14/2021 11:23:01 AM



Colorado Oil and Gas Conservation Commission

38.99128, -103.37712, 4839.2ft, 269°

09/14/2021 11:23:05 AM




Colorado Oil and Gas Conservation Commission
38.99128, -103.37712, 4839.2ft, 150°
09/14/2021 11:23:19 AM



Colorado Oil and Gas Conservation Commission
38.99089, -103.3778, 4796.6ft, 314°
09/14/2021 11:20:23 AM



Colorado Oil and Gas Conservation Commission
38.99093, -103.37778, 4832.7ft, 259°
09/14/2021 11:20:39 AM



Colorado Oil and Gas Conservation Commission
38.99076, -103.37691, 4852.4ft, 156°
09/14/2021 11:26:35 AM