

Caerus Piceance LLC
K8W
Location # 311645



Location/lack of battery signage



Glycol bath vessel not labeled



Caerus Piceance LLC
K8W
Location # 311645



Glycol bath vessel not labeled



Glycol bath vessel dimensions

Caerus Piceance LLC
K8W
Location # 311645




Glycol bath vessel dimensions



Glycol bath vessel dimensions



Caerus Piceance LLC
K8W
Location # 311645



Load out line



Load out line



Caerus Piceance LLC
K8W
Location # 311645



Open hole for wild life to enter



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
K8W
Location # 311645



Holes in containment



Holes in containment



Caerus Piceance LLC
K8W
Location # 311645



Holes in containment



Holes in containment

