

Final Reclamation Inspection

September 13, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 327274

Inspection Document #: 697503241

Weld County, CO

NWSE Section 20 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SUCCO GAS UNIT #4-20
Location ID: 327274




Photo 1. Google Earth aerial imagery taken 9/29/2020. Photo illustrates the well location (red circle) and western impacted area (orange circle). There is subsidence observed at the well location. The surface owner stated the subsidence is impacting flood irrigation and not getting irrigation water all the way to the west.

There were approximately 3, maybe more, potholes that have also subsided within the crop field where agricultural equipment is used.

Note- a final reclamation variance was granted for a portion of the western access road, access road southeast of property owner's house that goes to the former tank battery, and the tank battery.

Inspection Photos
Location Name: SUCCO GAS UNIT #4-20
Location ID: 327274



Photo 2. Photo taken from the well location, facing West. Photo illustrates subsidence at the well location.





Photo 3. Photo taken from one of the flowline potholes.



Photo 4. Photo taken from the tank battery, facing South. Photo illustrates tank battery has been utilized for the intended purpose for farm equipment storage. Location has been built upon and stabilized to minimize erosion.