

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334750



Photo #4868 from entrance to location.



Photo #4869 from entrance to location.



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334750



Photo #4066 from inspection #699803231 conducted on 6/11/21.



Photo #4870 No battery sign located at the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources