

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #4890 from entrance to location.



Photo #4891 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #4892 Glycol storage tank missing required information.



Photo #4893 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #4894 Location lacks stabilization.



Photo #4895 insufficient tracking control at entrance to location.