

# Final Reclamation Inspection

September 13, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 335731

Inspection Document #: 697503259

Adams County, CO

NENW Section 13 T1S R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NORTH COLORADO-61S68W 13NENW

Location ID: 335731



**Photo 1.** Photo taken from the northwestern location, facing North. Photo illustrates weed management is required. A wooden fence and gated entrance has been installed as part of the final reclamation activities.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697503259



# Inspection Photos

Location Name: NORTH COLORADO-61S68W

13NENW

Location ID: 335731



**Photo 2.** Photo taken from the northwestern location, facing Southwest. See comments under Photo 1.

Note- the observed equipment from the previous inspection has been removed.



**Photo 3.** Photo taken from the northwestern location, facing South. See comments under Photo 1 and 2.



Inspection Photos  
Location Name: NORTH COLORADO-61S68W  
13NENW  
Location ID: 335731



**Photo 4.** Photo taken from the southern location, facing South.  
See comments under Photo 1.



**Photo 5.** Photo taken from the eastern location, facing East.  
See comments under Photo 1.