

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Colorado Oil & Gas Conservation Commission
Weld County
+40.905389, -104.542433
2021-09-14 15:42

Photo #1


Little Lady 21 /North Well Pad

7: Wellsites

2: Producing | PR

5: Approved Permit to Drill | XX

Active: Not Drilled



Colorado Oil & Gas Conservation Commission
Weld County
+40.905268, -104.542598
2021-09-14 15:36

Photo #2

Little Lady 21-3NH (05-123-49875) Wellsite

Producing | PR

Well sign NOT posted

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Photo #3

Little Lady 21-5NH (05-123-49873) Wellsite

Producing | PR

Well sign NOT posted



Photo #4

Little Lady 21-3NH, 21-5NH

Battery site

Active

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Photo #5

Little Lady 21-3NH, 21-5NH

Battery site

Active

Compressors, Separators



Photo #6

Little Lady 21-3NH, 21-5NH

Battery site

Small Propane tank?

Contents, Hazard placards NOT posted

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Photo #7

Little Lady 21-3NH, 21-5NH

Battery site

Active

Battery sign, Invalid Contact Number



Photo #8

Little Lady 21-5NH

Wellsite

**Stained soil, Unnecessary Equipment
(various fittings, etc.)**

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Photo #9

Little Lady 21-3NH, 21-5NH

Wellsites

Portable Tanks

Stained soil, Unnecessary Equipment, Trash



Photo #10

Little Lady 21-3NH, 21-5NH

Battery site

East side

Stained soil, Trash

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Colorado Oil & Gas Conservation Commission
Weld County
+40.904067 - 104.541918
2021-09-14 16:07

Photo #11

Little Lady 21-3NH, 21-5NH

Battery site

East side

~ 100 yds. area

Unnecessary Equipment, Trash



Colorado Oil & Gas Conservation Commission
Weld County
+40.905305 - 104.541976
2021-09-14 16:03

Photo #12

Little Lady 21-3NH, 21-5NH

Battery site

East side

**Unnecessary Equipment
(Chemical Equipment)**

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Colorado Oil & Gas Conservation Commission
+40.905666,-104.542658
2021-09-14 16:21

Photo #13

Little Lady 21-3NH, 21-5NH

Battery site

Compressors

Stained soil



Colorado Oil & Gas Conservation Commission
Weld County
+40.904246,-104.543045
2021-09-14 16:23

Photo #14

Little Lady 21-3NH, 21-5NH

Battery site

3 Separators: Dog houses

Stained soil

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Photo #15

Little Lady 21-3NH, 21-5NH

Battery site

Separator berms: East side

Stained soil, trash



Photo #16

Little Lady 21-3NH, 21-5NH

Battery site

Tanks: Northwest side

Stained soil

Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location #: 462908



Colorado Oil & Gas Conservation Commission
Weld County
+40.904169, -104.542960
2021-09-14 16:25

Photo #17

Little Lady 22-1NH, 22-2CH

Battery site

Tanks: West side

Stained soil