

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402814265

Date Received:

09/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

Adamczyk, Megan

megan.adamczyk@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 700300270

Inspection Date: 09/10/2021

FIR Submit Date: 09/14/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306783

Location Name: COLE,JAMES GAS UNIT B-N34N8W Number: 8SWSW County: LA PLATA

Qtrqtr: SWS Sec: 8 Twp: 34N Range: 8W Meridian: N  
W

Latitude: 37.225700 Longitude: -107.773836

FACILITY - API Number: 05-067- -00 Facility ID: 264756

Facility Name: JAMES COLE B Number: 2

Qtrqtr: SWS Sec: 8 Twp: 34N Range: 8W Meridian: N  
W

Latitude: 37.225700 Longitude: -107.773836

CORRECTIVE ACTIONS:

2 CA# 155775

Corrective Action: Repair or replace deteriorated sound panel/sound mitigation materials (see photois), use engineered materials and maintain with best engineering practices with an emphasis to low frequency (c-scale) noise.

Date: 09/21/2021

Response: CA COMPLETED

Date of Completion: 09/15/2021

replaced and/or repaired insulation in panel. see photo attached.

CA completed
--------------

Print Name: Karin Rhodes Signed:

Signed:

Date: 9/16/2021 1:37:20 PM

□ □ □    1 2 3 4 5