

Final Reclamation Inspection

August 25, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 307213

Inspection Document #: 7019000076

Weld County, CO

NESW Section 25 T4N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ryan 23-25U
Location ID: 307213




Photo 1. 2019 aerial imagery of the well head and access road (north is up). Farmers old access road designated with blue line, well head access road designated with red line. Note: Tank battery is associated with a different well: API # 123-06334.

Inspection Photos
Location Name: Ryan 23-25U
Location ID: 307213




Photo 2. Overview photo of well head, access road and reference area taken from east of well head using a drone (north is right). Note: bare patch in majority of well disturbance pad.

Inspection Photos
Location Name: Ryan 23-25U
Location ID: 307213




Photo 3. Ground photo taken west of the well head looking east down access road.