

**Inspection Photos**  
**Location Name: USA 21-6**  
**Location ID: 318871**



**Photo 1 – Pumping Unit**



**Photo 2 – Wellhead Sign**



**Inspection Photos**  
**Location Name: USA 21-6**  
**Location ID: 318871**



**Photo 3 – Tank Battery**



**Photo 4 – NFPA Label has faded no longer visible**





**Inspection Photos**  
**Location Name: USA 21-6**  
**Location ID: 318871**



**Photo 5 – Tank Battery Sign**



**Photo 6 – Stained Soil at Crude Oil Tank**

**Inspection Photos**  
**Location Name: USA 21-6**  
**Location ID: 318871**



**Photo 7 – Heater Treater**




**Photo 8 – Pit**





**Inspection Photos**  
**Location Name: USA 21-6**  
**Location ID: 318871**



**Photo 9 – Oil Waste**