

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 3 Stained soil around WH

Photo 4 pump jack

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 5 Stained soil under gas engine in pump jack base

Photo 6 Gas engine

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 7 TB sign

Photo 8 TB

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 9 Compressor house

Photo 10 Compressor

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 11 Compressor house

Photo 12 Trash in Compressor house

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 13 Horizontal Heated Separator

Photo 14 PW tank

Inspection Photos
Location Name: Earl Anderson 2
Location ID: 336421



Photo 15 Stained soil around PW tank