

Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 3 Pump jack



Photo 4 Stained soil inside PJ base under gas engine

Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 5 Stained soil under gas engine in pump jack base



Photo 6 Gas engine

Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 7 TB sign



Photo 8 TB



Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 9 Compressor house



Photo 10 Compressor

Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 11 Compressor house



Photo 12 Trash in Compressor house

Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 13 Horizontal Heated Separator



Photo 14 PW tank

Inspection Photos
Location Name: Earl Anderson 1
Location ID: 336211



Photo 15 Stained soil around PW tank