

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2021

Submitted Date:

09/23/2021

Document Number:

696105054

FIELD INSPECTION FORM

Loc ID 415940 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416035	WELL	SI	03/01/2020	OW	123-31237	DILLARD USX AB 09-99HZ	SI

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Shut-In | SI.
Battery: Active.

Centralized Battery serves 2 Location IDs (415940, 415930).
(Well(s): 1: Shut-In | SI ; 1: Producing | PR).

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Paraffin Dispersant.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel w/ barbed wire.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	PUMP JACK		

Comment:	Iron panel.	Date:	
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.	Date:	
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 3		
Comment:	ECD #1, 2: Crude storage vapor line combustor. Controls crude oil tanks vapors. ECD #3: Separator vapor line combustor. Controls separator vapors. Pilots: ON		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	East: Meter removed. Inactive. West: Calibration card indicates calibration within last year. Last calibration: 01/06/2021. Active w/ production.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	At wellsite: 1: Paraffin Dispersant pump, tank w/ drip containment. Placards. At Battery site: 2: ECD scrubbers. 1: Electric power bank.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor drives pump jack. Shut-down.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 2 Location IDs (415940, 415930).				

Corrective Action:	Date:
--------------------	-------

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		40.593903,-104.563392

Comment:	Equalizer lines connect 4 of 5 crude oil tanks.	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O vaults.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	5	<100 BBLs	CONCRETE SUMP/VAULT		

Comment:		
Corrective Action:		Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	60 Bbls.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil tanks.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 416035 Type: WELL API Number: 123-31237 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI
Observed production valves shut.
COGCC records indicate last production: 02/2020.
Locked-Out, Tagged-Out | LOTO.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 01/22/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 09/20/2021 at approximately 15:14 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Dillard USX AB /09-99HZ Location ID: 415940 Well Name(s): Dillard USX AB 09-99HZ. API: 05-123-31237. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (415940, 415930). (Well(s): 1: Shut-In SI ; 1: Producing PR).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/23/2021

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105055	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5539212