

# Inspection Photos

API: 071-06657

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/23/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06657 | Date: 9/23/2021

## Inspection Photos



**Photo 1.** Facing southwest along the main road. There is rocks that have fallen into the road way.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06657 | Date: 9/23/2021



## Inspection Photos



**Photo 2.** The side of the main road is eroded and not stabilized. Lat/Long:37.10084,-104.789327.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06657 | Date: 9/23/2021



## Inspection Photos



**Photo 3.** Further along the main road. Stormwater has caused erosion along the roadside. This area may need a culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06657 | Date: 9/23/2021



## Inspection Photos



**Photo 4.** The side of the main road has eroded and is unstable. This area needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 5.** The cattle guard at Lat/Long:37.08881,-104.78996; is in disrepair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06657 | Date: 9/23/2021

## Inspection Photos



**Photo 6.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06657 | Date: 9/23/2021