




- Photo 1 –





- Photo 2 – Oil stained soil within tank battery





- Photo 3 – Oil stained soil at wellhead





- Photo 4 – Oil stained soil at wellhead