

**Inspection Photos**  
**Location Name: May 32-6**  
**Location ID: 320057**



**Pic 1 mechanical issue at wellhead oil is leaking on ground.**



**Pic 2 trash, stained soil, no containment under barrel.**



**Inspection Photos**  
**Location Name: May 32-6**  
**Location ID: 320057**



**Pic 3 Stained soil/ mechanical issue by wellhead.**



**Pic 4 stained soil/mechanical issue**



**Inspection Photos**  
**Location Name: May 32-6**  
**Location ID: 320057**

Sep 21, 2021 at 2:36:14 PM  
40.000541,-104.475808  
Keenesburg CO 80643  
United States  
COGCC



**Pic 5 gas meter run calibrated 7/21**

Sep 21, 2021 at 2:36:39 PM  
40.000538,-104.476088  
Keenesburg CO 80643  
United States  
COGCC



**Pic 6 stained soil under loadout valve.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: May 32-6**  
**Location ID: 320057**



**Pic 7 stained soil under loadout line.**



**Pic 8 stained soil / mechanical issue on back of tank.**