

Inspection Photos
Location Name: Federal Sandwash 2-1
Location ID: 313040



Photo 1. Overview of location taken facing east.



Inspection Photos
Location Name: Federal Sandwash 2-1
Location ID: 313040



Photo 2. Tank with holes.



Photo 3. Close up of photo 2 and tank holes. Tank has become debris and must be removed.



Inspection Photos
Location Name: Federal Sandwash 2-1
Location ID: 313040



Photo 4. No bradenhead access apparent.



Photo 5. Tank knocked over and off secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources