

**Inspection Photos**  
**Location Name: Visintainer 11-6-8-90**  
**Location ID: 313235**



**Photo 1. Overview of location taken facing north.**

**Inspection Photos**  
**Location Name: Visintainer 11-6-8-90**  
**Location ID: 313235**



**Photo 2. No bradenhead access apparent.**



**Photo 3. Gas meter not calibrated annually. Last calibration 6/2020.**