

Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 1. Overview of location taken facing east.



Photo 2. No wellhead sign. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297




Photo 3. No bradenhead access apparent. Stained soil at wellhead.



Photo 4. Buckets that appear to be trash at pump jack. Stained soil at pump jack.



Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 5. Incomplete tank labels.



Photo 6. Incomplete tank labels.



Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 7. Stained soil at loadout.



Photo 8. Stained soil at loadout.

