

Inspection Photos
Location Name: Lasher 9
Location ID: 313178



Photo 1. Former BMPs remain as debris.



Photo 2. Former BMPs remain as debris.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources