

Final Reclamation Inspection

September 24, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328004

Inspection Document #: 697503293

Weld County, CO

SENW Section 12 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: ODENBAUGH #12-6L

Location ID: 328004



Photo 1. 2019 aerial imagery illustrates the well location and associated tank battery (red circles). The well location access road traveling south from the tank battery has not been reclaimed and was not pre-existing prior to oil and gas development. Refer to the following aerial imagery.



Inspection Photos
Location Name: ODENBAUGH #12-6L
Location ID: 328004



Photo 2. Aerial imagery taken 10/13/1984 prior to oil and gas activities. Photo illustrates that prior to oil and gas activities the well location access road did not exist.

Inspection Photos
Location Name: ODENBAUGH #12-6L
Location ID: 328004



Photo 3. Photo taken from the northern well location access road, facing South. Photo illustrates the well location access road has not been reclaimed.

Inspection Photos
Location Name: ODENBAUGH #12-6L
Location ID: 328004



Photo 4. Photo taken from the well location, facing South. Photo illustrates the well location has not been reclaimed.

Inspection Photos
Location Name: ODENBAUGH #12-6L
Location ID: 328004



Photo 5. Photo taken of the associated offsite tank battery location, facing East. Photo illustrates the tank battery is still use for other nearby wells.