

Mull Drilling Company INC, BSR A 1-19
073-06779

Inspection #688311215

9/27/2021


Surface Cementing Inspection




COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
38.99149, -103.37733, 4852.4ft, 183°
09/26/2021 09:50:00 PM



Colorado Oil and Gas Conservation Commission
38.99134, -103.37734, 4872.0ft, 184°
09/26/2021 09:50:15 PM



Colorado Oil and Gas Conservation Commission
38.99131, -103.37747, 4872.0ft, 308°
09/26/2021 09:50:36 PM




Colorado Oil and Gas Conservation Commission
38.99129, -103.37747, 4852.4ft, 354°
09/26/2021 09:50:52 PM



Colorado Oil and Gas Conservation Commission
38.99052, -103.37747, 4842.5ft, 184°
09/27/2021 06:36:19 AM




Colorado Oil and Gas Conservation Commission
38.99059, -103.37756, 4872.0ft, 283°
09/27/2021 06:36:39 AM



Colorado Oil and Gas Conservation Commission
38.99098, -103.37766, 4872.0ft, 211°
09/27/2021 08:41:43 AM



Colorado Oil and Gas Conservation Commission
38.99058, -103.37757, 4862.2ft, 356°
09/27/2021 06:36:47 AM



Colorado Oil and Gas Conservation Commission
38.99153, -103.37735, 4973.8ft, 183°
09/27/2021 06:41:28 AM



Colorado Oil and Gas Conservation Commission
38.99132, -103.37773, 4872.0ft, 172°
09/27/2021 06:52:57 AM



Colorado Oil and Gas Conservation Commission
38.99058, -103.37757, 4862.2ft, 268°
09/27/2021 06:38:37 AM



Colorado Oil and Gas Conservation Commission
38.99059, -103.37756, 4839.2ft, 318°
09/27/2021 06:38:50 AM