



- Photo 1 –





- Photo 2 –





- Photo 3 – Petroleum stained soil north, northeast corner of tank battery





- Photo 4 – Petroleum stained soil north, northeast corner of tank battery





- Photo 5 – Petroleum stained soil north, northeast corner of tank battery





- Photo 6 – Petroleum stained soil north side of tank battery, view east



- Photo 7 –





- Photo 8 –





- Photo 9 –