

**Inspection Photos**  
**Location Name: Stark 18-13**  
**Location ID: 320379**



**Photo #1 Tanks.**



**Photo #2 Separator.**

**Inspection Photos**  
**Location Name: Stark 18-13**  
**Location ID: 320379**



**Photo #3 Pump Jack**



**Photo #4 stained soil under load off line.**