

Final Reclamation Inspection

September 9th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 333191

Inspection Document #: 698400014

Weld County, CO

NESE Section 13 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Watters 13-9B
Location ID: 333191



Photo 1. 2019 aerial imagery shows the well head, tank battery and associated access road (north is up). Note: the access road was built prior to the highway getting built.

Inspection Photos
Location Name: Watters 13-9B
Location ID: 333191



Photo 2. Overview photo of well head and reference area taken northwest of well head, looking southeast. Photo shows the vegetation within the well head and along the access road appear consistent with adjacent reference area.

Inspection Photos
Location Name: Watters 13-9B
Location ID: 333191



Photo 3. North and East photos taken at ground level from middle of well head.

Inspection Photos
Location Name: Watters 13-9B
Location ID: 333191



Photo 4. South and west photos taken at ground level from the middle of the well head.

Inspection Photos
Location Name: Watters 13-9B
Location ID: 333191



Photo 5. Overview photo taken of tank battery and reference area using a drone (west is up). Photo shows heavy equipment vehicle tracks and very little plant growth (see following photos for closeups).

Inspection Photos
Location Name: Watters 13-9B
Location ID: 333191



Photo 6. North and East photos taken at ground level from east portion of tank battery.

Inspection Photos
Location Name: Watters 13-9B
Location ID: 333191



Photo 7. South and west photos taken at ground level from the middle of the tank battery.