

Final Reclamation Inspection

September 9th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322815

Inspection Document #: 698400015

Weld County, CO

NWSW Section 17 T5N R64W

Logan McConnell
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dunn/Miller 1
Location ID: 322815



Photo 1. 2021 aerial imagery shows the well head, tank battery and associated access road (north is up).

Inspection Photos
Location Name:Dunn/Miller 1
Location ID: 322815



Photo 2. Overview photo of well head and reference area taken northwest of well head, looking southeast. Photo shows the vegetation within the well head and along the access road appear consistent with adjacent reference area.

Inspection Photos
Location Name: Dunn/Miller 1
Location ID: 322815




Photo 3. North and East photos taken at ground level from middle of well head.

Inspection Photos
Location Name:Dunn/Miller 1
Location ID: 322815



Photo 4. South and west photos taken at ground level from the middle of the well head.

Inspection Photos
Location Name:Dunn/Miller 1
Location ID: 322815



Photo 5. Reference photo taken from the northwest corner of the well head, looking northeast away from the well head.

Inspection Photos
Location Name:Dunn/Miller 1
Location ID: 322815



Photo 6. Photo of the tank battery location, looking south through the landowners gate. The tank battery location had a land use change, the area is completely fenced in, and is now used for residential housing (address: 27402 County Road 51, Greeley, CO).