

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX /SG 31-32

Location ID: 334395



Photo #4992 from entrance to location.



Photo #4993 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX /SG 31-32

Location ID: 334395



**Photo #4994 No tank battery sign located at the tank battery.**



**Photo #4995 Glycol storage tank missing required information.**





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX /SG 31-32

Location ID: 334395



Photo #4996 Gauge hatch open.



Photo #4997 Location lacks stabilization.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX /SG 31-32

Location ID: 334395



**Photo #4998 Location lacks stabilization.**



**Photo #4999 No form of tracking BMP located at the entrance to location.**