

Final Reclamation Inspection

August 11th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322862

Inspection Document #: 701900131

Weld County, CO

NWNW Section 17 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Schaumberg 1
Location ID: 332862



Photo 1. 2019 aerial imagery of the well pad (north is up). Tank battery (highlighted in blue) is associated with well API # 123-18878 not pictured to the south.

Inspection Photos
Location Name: Schaumberg 1
Location ID: 332862




Photo 2. Overview photo of the well pad and reference area taken from the southern end of the well pad using a drone. Photo shows that the well pad appears consistent with the reference area.

Inspection Photos
Location Name: Schaumberg 1
Location ID: 332862




Photo 3. Ground photo taken from the west of the well pad.

