

Inspection Photos
Operator: Simcoe
Facility: 067-08826
Date: 9/20/2021



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of western project area from the southwestern corner facing northward. Revegetation is progressing with smooth brome, bluebunch wheatgrass, western wheatgrass, and fringed sage.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Approximately 150 musk thistles, kochia, and Russian thistle weeds present. Little desirable vegetation here.



Photo 4. View of musk thistle rosettes (next to boot) within the southwestern project area.




Photo 5. View of flowering musk thistles within the southern project area.




Photo 6. View of more musk thistles growing along the pipeline ROW.



Photo 7. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland with James galleta, rubber rabbitbrush, snakeweed, Indian paintbrush, and squirreltail.