

Inspection Photos
Operator: Simcoe
Facility: 067-08782
Date: 9/20/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revgetation is progressing with sand dropseed, western wheatgrass, Indian ricegrass, and rubber rabbitbrush.



Photo 3. View of erosional channel along the access road up to 3ft wide and deep needing stabilization. Erosional scouring, downcutting, and sediment transport observed.



Photo 4. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland with James galleta, rubber rabbitbrush, snakeweed, Indian paintbrush, and squirreltail.