

Inspection Photos

Location Name: Rowe 01N-65W-26-8N

Location ID: 441092

Oct 6, 2021 at 12:37:07 PM
40.029287,-104.632979
Hudson CO 80642
United States
COGCC



Pic 1 Separator, gas meter run, compressor, IOT automation equipment.

Oct 6, 2021 at 12:37:25 PM
40.029257,-104.632706
Hudson CO 80642
United States
COGCC



Pic 2 tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Rowe 01N-65W-26-8N
Location ID: 441092

Oct 6, 2021 at 12:37:29 PM
40.029257,-104.632706
Hudson CO 80642
United States
COGCC



Pic 3 ECD

Oct 6, 2021 at 12:37:43 PM
40.029090,-104.632598
Hudson CO 80642
United States
COGCC



Pic 4 wellhead